## Spare parts list

## Categories explanation\*

Wear & Tear: Spare parts that should be replaced periodically on maintenance and service; listed with recommended replacement frequencies in month.

Strategic: Recommended spare parts on site for clients needing high availability all the time, facing no delays due to transportation or customs.

Optional: Spare parts that should not break, listed for completeness.

Please note: In case maintenance and service is not fulfilled according to manual's instructions, warranty claims can not be accepted. Our spare parts deliveries are usually delivered with DHL express.

Parts orders or further information requests to be addressed to our customer care team: info@curio.group

Qty	Article no.	Item	Category*	Family	Replacement frequency (month)
1	6393800000	HUBLOT POUR XF EN PYREX		С	
1	6393200000	JOINT VITON POUR HUBLOT XF DIAM 200 MM		В	
1	2620022331	HV TROUGH BUSHING FULL CERAMIC BIG FOR OZONE GEN. (TYPE XF/XFR)		D	
1	6392700000	JOINT DE BORNE HAUTE TENSION		В	
3	2620010004	DIELECTRIC AT 95 – 540 MM with CAMS for at VESSEL		D	
1	6387700000	HV FUSE - 120 TD 0.5		С	
1	6396800000	JOINT DE FOND DIAM 12 - XF2 ET 6 - DIAM INT.756 5		В	
1	6351500000	METRE DE BANDE POUR OZONEUR XF		С	
1	3383000000	THREADED ROD IN STAINLESS STEEL LONG. 2205		В	
1	3383400000	WASHER M4 ALUMINIUM for DIELECTRIC		В	









